THIS YEAR IN

MOTOR

An index of more than 400 sales, management and service articles that have appeared in this magazine in 1971

Month Page



Month Page



Month Page

Tu

EN

H

Q

0

He

N

T

N

SERVICE PROCEDURES

ACCESSORIES Month Page Takes Kinks Out of Tubing (F) Jan. 27 Cadillac Blower Motor Squeal (S) 32 Feb. Sell This 10-Point Air Conditioner Tune-Up 37 Apr. Exploding 5 Air Conditioning Service Myths Apr. 38 Substitute for Lost Snap Ring (F) Apr. 58 Rainy-Day Radio Interference (S) June Wrong Airflow from Air Conditioner (F) 30 Aug. Dodge Windshield-Wiper Blade Installation (S) 62 Aug. Chrysler Speedometer Cable Service (S) Aug. 64 Oldsmobile Wiper Control Button Replacement (S) .. Aug. 64 Correcting Cadillac Instrument Panel "Hiss" (S) Sept. 30 Dodge Horn Blows When Hot (S) Sept. 30 Test Procedure for Stalled Mercury Wiper (S) Sept. 30 Blower Problem on Chevrolet Air Conditioner (F) 30 Dec.

AXLES

Trailer Towing Can Affect Cadillac Differential		
Lubricant (S)	Apr.	2
Plymouth Rear Axle		
Identification (S)	Apr.	2
Rear Wheel Alignment		
(Import Info)	May	5
Correcting Oldsmobile Rear		
End Noise (S)	Sept.	3

BODY AND FRAME

Chevrolet Door Glass "Blow-Out" Plate		
Replacement (S)	Jan.	48
GM Fender Molding		
Installation (F)	Jan.	48
Salvage Air Chisels (F)		41
Camaro Windshield Molding		
Screw Removal (S)	May	1:
Pontiac Steering Column		
Repair (S)	May	1:
Window Leak Test (F)	May	1:
Prevents Scratches on		
Refinish Jobs (F)	May	13
Lincoln-Mercury Door Pull		-
Handle Retention (S)	June	2
Pontiac Endura Bumper		_
Paint Repair (S)	June	2

Installation (F)	June	20
Faster Fender Fix		
for Olds 88 (F)	June	26
Plymouth Valiant Grille Repair		
Now Possible (S)	July	24
Non-Rusting Molding		
Installation (F)	July	24
Pontiac Front Bumper Face-Bar		
Removal (S)	Aug.	38
Chrysler Tailgate Autolock		
Solenoid Adjustment (S)	Aug.	38
Camaro Window-Regulator		
Replacement Change (S)	Aug.	38
Cadillac Glove-Box Liner		
Removal (S)	Aug.	38
Window Regulator Repair		-
	Aug.	38
Tip (F) Pulling It All Together	Oct	46
Tomay to Am Togottor		
BRAKES		
Takes Kinks Out of Tubing (F)	Jan.	27
Pinto's Disc Brakes Are Different		37
Buick Wheel Cylinder Piston	midi.	0,
Damage (S)	Apr.	24
Mercury Master Cylinder	Apri.	2-4
Diagnosis (S)	June	10
Dust Boot Installation on	Jone	10
Kelsey-Hayes Disc (F)	Tube	28
Power Brake Tester (F)	Aug	30
Discs, the Brake of the Future	Aug.	30
-Are You Ready to		
	A	42
Service Them?	Aug.	43
		47
Specifications	Aug.	47
Bleeding Drum and Disc Brakes	Aug.	48
1965-71 Rotor Specifications	Aug.	96
Correcting Oldsmobile Rear		'00
End Noise (S)	Sept.	30
Working on Ford Brakes	Sept.	60
Chrysler Floating Caliper	-	
Removal (S)	Dec.	20
COOLING SYSTEM		
Cougar Gauges Read High (S)	Jan.	58

Easier Windshield Glass

condat Gandes Keaa Lildii (3)	Jun.	20
Switched Gasket Causes		
Water-Pump Leak	Mar.	22
Oldsmobile Upper Bypass		
Hose Repair Kit (S)	May	28
10 Quick Service Steps for		
Truck Cooling Systems	Oct.	72
Water Pump Removal on		
GMC Truck (F)	Dec.	30

DRIVESHAFT AND UNIVERSAL JOINT

Change in Ol	dsmol	bile		
Ring-Gear	Bolts	(S)	 Jan.	

ELECTRICAL SYSTEM


Fred Total Control Dates		
Ford Truck Starter Drive Tip (F)	Jan.	27
Tip (F) Takes Kinks Out of Tubing (F)	Jan.	27
Improving Your Aim	Jan.	44
Capri Replacement Battery		
Installation (S)	Jan.	57
How to Time the Imports		
(Import Info)	Feb.	6
Mercury Bulb Burn-Out on		
Booster Starts (S)	Feb.	32
Change in Chrysler Wiring		
Circuit (S)	Mar.	22
Dead Battery Again (F)	Mar.	30
Prevents Alternator Damage (F)	Mar.	34
How to Replace VW Lights		
(Import Info)	Mar.	70
Hood Bolt Causes Chevrolet		
Regulator Failure (S)	Apr.	26
Spark Plug Removal on		
Pontiac (F)	Apr.	58
Eliminates Play in GM 6 cyl.		
Distributor (F)	Apr.	58
Capri Hard Starting Cold (S)	May	26
Cadillac Eldorado Wiring		
Diagram Correction (S)	May	28
Where to Find All Types of		
Circuit Protection	May	50
Why '71 Distributor Specs		
Are Different	May	74
Jeep Alternator Indicator		
Bulb Glows (S)	June	10
Put Secondary Wiring First	June	44
Flasher Locations	June	46
GM Distributor Check (F)	July	28
Tune-Up Data on 1971 Cars	July	48
How to Tune the VW		
(Import Info)	July	52
Chevrolet Taillamp Socket		
Replacement (S)	July	62
Better Lighting in Oldsmobile		
Instrument Panel (S)	July	62
Capri Instrument Gauge		
Diagnosis (S)	July	64
Rating Batteries Under the		
New Standards	Aug.	55
Tuning Up the Opel		-
(Import Info)	Aug.	51
Ford Econoline Ignition		
Timing Change (S)	Aug.	6
Toronado Taillamp Socket		
Removal (S)	Aug.	6
Wandering Needle on		
Voltmeter (S)	Aug.	6
Tuning Up the Toyota		
(Import Info)	Sept.	6
Tuning Up the Volvo		
(Import Info)	Oct.	5
Erratic Charge Indicator		

THIS YEAR IN

MOTOR

An index of more than 400 sales, management and service articles that have appeared in this magazine in 1971

Month Page



Month Page



Month Page

Tu

EN

H

Q

0

He

N

T

N

SERVICE PROCEDURES

ACCESSORIES Month Page Takes Kinks Out of Tubing (F) Jan. 27 Cadillac Blower Motor Squeal (S) 32 Feb. Sell This 10-Point Air Conditioner Tune-Up 37 Apr. Exploding 5 Air Conditioning Service Myths Apr. 38 Substitute for Lost Snap Ring (F) Apr. 58 Rainy-Day Radio Interference (S) June Wrong Airflow from Air Conditioner (F) 30 Aug. Dodge Windshield-Wiper Blade Installation (S) 62 Aug. Chrysler Speedometer Cable Service (S) Aug. 64 Oldsmobile Wiper Control Button Replacement (S) .. Aug. 64 Correcting Cadillac Instrument Panel "Hiss" (S) Sept. 30 Dodge Horn Blows When Hot (S) Sept. 30 Test Procedure for Stalled Mercury Wiper (S) Sept. 30 Blower Problem on Chevrolet Air Conditioner (F) 30 Dec.

AXLES

Trailer Towing Can Affect Cadillac Differential		
Lubricant (S)	Apr.	2
Plymouth Rear Axle		
Identification (S)	Apr.	2
Rear Wheel Alignment		
(Import Info)	May	5
Correcting Oldsmobile Rear		
End Noise (S)	Sept.	3

BODY AND FRAME

Chevrolet Door Glass "Blow-Out" Plate		
Replacement (S)	Jan.	48
GM Fender Molding		
Installation (F)	Jan.	48
Salvage Air Chisels (F)		41
Camaro Windshield Molding		
Screw Removal (S)	May	1:
Pontiac Steering Column		
Repair (S)	May	1:
Window Leak Test (F)	May	1:
Prevents Scratches on		
Refinish Jobs (F)	May	13
Lincoln-Mercury Door Pull		-
Handle Retention (S)	June	2
Pontiac Endura Bumper		_
Paint Repair (S)	June	2

Installation (F)	June	20
Faster Fender Fix		
for Olds 88 (F)	June	26
Plymouth Valiant Grille Repair		
Now Possible (S)	July	24
Non-Rusting Molding		
Installation (F)	July	24
Pontiac Front Bumper Face-Bar		
Removal (S)	Aug.	38
Chrysler Tailgate Autolock		
Solenoid Adjustment (S)	Aug.	38
Camaro Window-Regulator		
Replacement Change (S)	Aug.	38
Cadillac Glove-Box Liner		
Removal (S)	Aug.	38
Window Regulator Repair		-
	Aug.	38
Tip (F) Pulling It All Together	Oct	46
Tomay to Am Togottor		
BRAKES		
Takes Kinks Out of Tubing (F)	Jan.	27
Pinto's Disc Brakes Are Different		37
Buick Wheel Cylinder Piston	midi.	0,
Damage (S)	Apr.	24
Mercury Master Cylinder	Apri.	2-4
Diagnosis (S)	June	10
Dust Boot Installation on	Jone	10
Kelsey-Hayes Disc (F)	Tube	28
Power Brake Tester (F)	Aug	30
Discs, the Brake of the Future	Aug.	30
-Are You Ready to		
	A	42
Service Them?	Aug.	43
		47
Specifications	Aug.	47
Bleeding Drum and Disc Brakes	Aug.	48
1965-71 Rotor Specifications	Aug.	96
Correcting Oldsmobile Rear		'00
End Noise (S)	Sept.	30
Working on Ford Brakes	Sept.	60
Chrysler Floating Caliper	-	
Removal (S)	Dec.	20
COOLING SYSTEM		
Cougar Gauges Read High (S)	Jan.	58

Easier Windshield Glass


condat Gandes Keaa Lildii (3)	Jun.	20
Switched Gasket Causes		
Water-Pump Leak	Mar.	22
Oldsmobile Upper Bypass		
Hose Repair Kit (S)	May	28
10 Quick Service Steps for		
Truck Cooling Systems	Oct.	72
Water Pump Removal on		
GMC Truck (F)	Dec.	30

DRIVESHAFT AND UNIVERSAL JOINT

Change in Ol	dsmol	bile		
Ring-Gear	Bolts	(S)	 Jan.	

ELECTRICAL SYSTEM

Fred Total Control Dates		
Ford Truck Starter Drive Tip (F)	Jan.	27
Tip (F) Takes Kinks Out of Tubing (F)	Jan.	27
Improving Your Aim	Jan.	44
Capri Replacement Battery		
Installation (S)	Jan.	57
How to Time the Imports		
(Import Info)	Feb.	6
Mercury Bulb Burn-Out on		
Booster Starts (S)	Feb.	32
Change in Chrysler Wiring		
Circuit (S)	Mar.	22
Dead Battery Again (F)	Mar.	30
Prevents Alternator Damage (F)	Mar.	34
How to Replace VW Lights		
(Import Info)	Mar.	70
Hood Bolt Causes Chevrolet		
Regulator Failure (S)	Apr.	26
Spark Plug Removal on		
Pontiac (F)	Apr.	58
Eliminates Play in GM 6 cyl.		
Distributor (F)	Apr.	58
Capri Hard Starting Cold (S)	May	26
Cadillac Eldorado Wiring		
Diagram Correction (S)	May	28
Where to Find All Types of		
Circuit Protection	May	50
Why '71 Distributor Specs		
Are Different	May	74
Jeep Alternator Indicator		
Bulb Glows (S)	June	10
Put Secondary Wiring First	June	44
Flasher Locations	June	46
GM Distributor Check (F)	July	28
Tune-Up Data on 1971 Cars	July	48
How to Tune the VW		
(Import Info)	July	52
Chevrolet Taillamp Socket		
Replacement (S)	July	62
Better Lighting in Oldsmobile		
Instrument Panel (S)	July	62
Capri Instrument Gauge		
Diagnosis (S)	July	64
Rating Batteries Under the		
New Standards	Aug.	55
Tuning Up the Opel		-
(Import Info)	Aug.	51
Ford Econoline Ignition		
Timing Change (S)	Aug.	6
Toronado Taillamp Socket		
Removal (S)	Aug.	6
Wandering Needle on		
Voltmeter (S)	Aug.	6
Tuning Up the Toyota		
(Import Info)	Sept.	6
Tuning Up the Volvo		
(Import Info)	Oct.	5
Erratic Charge Indicator		









Month Page

Month Page

Month Page

						4 P 1 144 1 014
Light in Mustang (S)	Oct.	68	Sell Emission Control Service in '71	Jan.	36	Adjusting the Weber 2V Carburetor (Import Info)
Replacement (S)	Oct.	70	Champion to Fight Pollution			Carburetor Tune-Up in 10
	Nov.	26	With Cleaner Air Clinics	Feb.	120	Easy Steps
Tuning Up the Colt			Tool Power Lightens Exhaust			Capri Instrument Gauge
-(Import Info)	Nov.	37	System Service	Mar.	57	Diagnosis (S)
Tuning Up the Datsun			Tune-Up: Special Report			Fuel Recommendations for
(Import Info)	Dec.	52	90% Cleaner by 1975-			Chrysler (S)
FHAINE			An Impossible Dream?	July	37	Jeep Initial Choke-Adjustm
ENGINE			How Do Your Customers			Procedure Changed (S)
Causes of Pontiac Piston			Feel About Air Pollution?	July	39	Servicing Truck Air Cleane
Damage (S)	Jan.	57	Keeping All Systems Go	July	40	Is Not That Different
How to Install Hastings			Will You Be Ready When			Stalling Condition with
Bronze Valve Guide-Liner	Jan.	67	Your State Starts Testing			Rochester BC Carburetor
Quick Pinto Camshaft Timing			for Exhaust Emission	July	41	Chevrolet Quadra-Jet Fuel
Check (S)	Mar.	26	Leaded and Non-Leaded			Inlet Nut Repair (S)
More Elbowroom on Engine			Fuel: A View from the			Deceleration Valve
Work (F)	Mar.	30	Factories	July	42	Adjustment on Capri (S
Oil Prime on Ford Engine (F)	Mar.	34	Emission Control Hard-			Colt Carburetor Float Leve
How to Repair Aluminum-			ware: A Look at '72			Check (S)
Head Spark-Plug Ports	Mar.	50	and Beyond	July	43	Locating and Servicing Tru
Identify 1971 Engines Fast		46	Carburetor Tune-Up in			Fuel Filters
Head Bolt Torque on			10 Easy Steps		44	Pontiac Fuel Hose
Plymouth 318 V-8 (S)	May	26	Tune-Up Data on 1971 Cars	July	48	Installation (S)
10 Things a Vacuum Gauge			Oldsmobile Exhaust System			LUBBIGATION
Will Tell You About an			Service Recommendation		22	LUBRICATION
Engine	May	46	Don't Overlook PCV Service	Nov.	44	Servicing the Crankcase
Smoke Puff on Buick			Servicing Dodge Truck			(Import Info)
Start-Up (S)	June	8	Emission System	Dec.	40	Takes Kinks Out of Tubing
Repairing Spark-Plug Ports			FRONT FUR CTFFRING			Why Today's Oil Gets Tire
in 5 Easy Steps	June	64	FRONT END, STEERING			Faster
Aids Hydraulic Valve Lifter			Clamp Location for Chevrolet			Cougar Gauges Read Hig
Disassembly (F)		28	Tie Rod Sleeve (S)	Mar.	22	Oil Pan Removal on
Tune-Up Data on 1971 Cars	July	48	Camaro Lower Ball-Joint			Montego 429 Engine (S
How to Tune the VW			Inspection (S)	Mar.	22	Crankcase Seal Removal
(Import Info)	July	52	Oldsmobile Power-Steering			Vega Oil Pressure Sendin
New Crankshaft Oil Seal			Flow Control Valve			Unit Installation (\$)
for Dodge-Plymouth			Removal (S)	Mar.	26	Oldsmobile Oil Leak and
426 Hemi (S)	July	62	Five Easy Steps for			Tooth Pattern Diagnosis
Easier Water Drain on			Power-Steering Service	Mar.	46	Montega Oil Pan Remova
Chevrolet	Aug.	30	Front Wheel Alignment			New Trends in Lubrication
Tuning Up the Opel			(Import Info)	Apr.	52	Easier Oil Pan Removal (
(Import Info)	Aug.	58	VW Front Wheel Alignment,			Ford Lubrication Fitting
Checks Timing Mark	C	20	1968-71			Installation (F)
Accuracy (F)	Sept.	22	Front End Tune-Up	Oct.	37	
Tuning Up the Toyota	C-mt	66	1971-Wheel Alignment			Know When to Change
(Import Info)	Sept.	00	Specifications	Oct.		Truck Oil Filters
Tuning Up the Volvo	0-1	52	Wheel Balancing Tip (F)	Oct.	59	NEW CAR SERVICE
(Import Info)		26	Keep Your Customers' Wheels			
Easier Valve Lift Removal (F) Loose Harmonic Balancer	1404.	20	Spinning Safely	Nov	. 40	What's New in Servicing
on Buick (F)	Nov	26				the '71s
Tuning Up the Colt	1404.	10	FUEL SYSTEM			Engine
(Import Info)	Nov	37	Takes Kinks Out of Tubing (F)	Jan.	27	Body, Frame
Identify 1972 Engines Fast		50	Gets Good Gas Gauge	-		Tune-Up
Tuning Up the Datsun	500.		Ground (F)	Feb.	28	Drivetrain
(Import Info)	Dec	52	Warped Air Horn Causes			Brakes
			Stumble (S)	Apr	. 24	
EXHAUST EMISSION CONTROL			Substitute for Lost Snap Ring (F)			
Takes Kinks Out of Tubing (F)	lan	27	Quick Fix for Vapor Lock (F)			(S) = Service Slants
Takes Killiks Out of Tobing (F)	Juli.	21	GOIGH TIX TOT TOPOT LOCK (1)	- Inlin		10/ - 0011100 0101110

Sell Emission Control Service		
in '71	Jan.	36
Champion to Fight Pollution		
With Cleaner Air Clinics	Feb.	120
Tool Power Lightens Exhaust		
System Service	Mar.	57
Tune-Up: Special Report		
90% Cleaner by 1975—		
An Impossible Dream?	July	37
How Do Your Customers		
Feel About Air Pollution?	July	39
Keeping All Systems Go	July	40
Will You Be Ready When		
Your State Starts Testing		
for Exhaust Emission	July	41
Leaded and Non-Leaded		
Fuel: A View from the		
Factories	July	42
Emission Control Hard-		
ware: A Look at '72		40
and Beyond	July	43
Carburetor Tune-Up in 10 Easy Steps		
10 Easy Steps	July	44
Tune-Up Data on 1971 Cars	July	48
Oldsmobile Exhaust System		
Service Recommendation	Nov.	22
Don't Overlook PCV Service	Nov.	44
Servicing Dodge Truck Emission System	_	40
Emission System	Dec.	40
FRONT END, STEERING		
FRONT END, STEERING Clamp Location for Chevrolet Tie Rod Sleeve (S)	Mar.	22
FRONT END, STEERING Clamp Location for Chevrolet Tie Rod Sleeve (S)		22
FRONT END, STEERING Clamp Location for Chevrolet Tie Rod Sleeve (S)		22
FRONT END, STEERING Clamp Location for Chevrolet Tie Rod Sleeve (S)		
FRONT END, STEERING Clamp Location for Chevrolet Tie Rod Sleeve (S)		
FRONT END, STEERING Clamp Location for Chevrolet Tie Rod Sleeve (S)	Mar.	22
FRONT END, STEERING Clamp Location for Chevrolet Tie Rod Sleeve (S) Camaro Lower Ball-Joint Inspection (S) Oldsmobile Power-Steering Flow Control Valve Removal (S)	Mar.	22
FRONT END, STEERING Clamp Location for Chevrolet Tie Rod Sleeve (S) Camaro Lower Ball-Joint Inspection (S) Oldsmobile Power-Steering Flow Control Valve Removal (S)	Mar.	22
FRONT END, STEERING Clamp Location for Chevrolet Tie Rod Sleeve (5) Camaro Lower Ball-Joint Inspection (S) Oldsmobile Power-Steering Flow Control Valve Removal (S) Five Easy Steps for Power-Steering Service Front Wheel Alignment	Mar. Mar.	22 26
FRONT END, STEERING Clamp Location for Chevrolet Tie Rod Sleeve (5) Camaro Lower Ball-Joint Inspection (S) Oldsmobile Power-Steering Flow Control Valve Removal (S) Five Easy Steps for Power-Steering Service Front Wheel Alignment	Mar. Mar.	22 26
FRONT END, STEERING Clamp Location for Chevrolet Tie Rod Sleeve (S) Camaro Lower Ball-Joint Inspection (S) Oldsmobile Power-Steering Flow Control Valve Removal (S) Five Easy Steps for Power-Steering Service	Mar. Mar.	22 26 46
FRONT END, STEERING Clamp Location for Chevrolet Tie Rod Sleeve (S) Camaro Lower Ball-Joint Inspection (S) Oldsmobile Power-Steering Flow Control Valve Removal (S) Five Easy Steps for Power-Steering Service Front Wheel Alignment (Import Info) VW Front Wheel Alignment,	Mar. Mar. Apr.	22 26 46 52
FRONT END, STEERING Clamp Location for Chevrolet Tie Rod Sleeve (S) Camaro Lower Ball-Joint Inspection (S) Oldsmobile Power-Steering Flow Control Valve Removal (S) Five Easy Steps for Power-Steering Service Front Wheel Alignment (Import Info) VW Front Wheel Alignment, 1968-71 Front End Tune-Up	Mar. Mar. Apr. June	22 26 46 52
FRONT END, STEERING Clamp Location for Chevrolet Tie Rod Sleeve (S) Camaro Lower Ball-Joint Inspection (S) Oldsmobile Power-Steering Flow Control Valve Removal (S) Five Easy Steps for Power-Steering Service Front Wheel Alignment (Import Info) VW Front Wheel Alignment, 1968-71 Front End Tune-Up	Mar. Mar. Apr. June	22 26 46 52 71
FRONT END, STEERING Clamp Location for Chevrolet Tie Rod Sleeve (S) Camaro Lower Ball-Joint Inspection (S) Oldsmobile Power-Steering Flow Control Valve Removal (S) Five Easy Steps for Power-Steering Service Front Wheel Alignment (Import Info) VW Front Wheel Alignment, 1968-71 Front End Tune-Up 1971-Wheel Alignment	Mar. Mar. Apr. June Oct.	22 26 46 52 71
FRONT END, STEERING Clamp Location for Chevrolet Tie Rod Sleeve (S) Camaro Lower Ball-Joint Inspection (S) Oldsmobile Power-Steering Flow Control Valve Removal (S) Five Easy Steps for Power-Steering Service Front Wheel Alignment (Import Info) VW Front Wheel Alignment, 1968-71 Front End Tune-Up 1971-Wheel Alignment Specifications	Mar. Mar. Apr. June Oct.	22 26 46 52 71 37
FRONT END, STEERING Clamp Location for Chevrolet Tie Rod Sleeve (S) Camaro Lower Ball-Joint Inspection (S) Oldsmobile Power-Steering Flow Control Valve Removal (S) Five Easy Steps for Power-Steering Service Front Wheel Alignment (Import Info) VW Front Wheel Alignment, 1968-71 Front End Tune-Up 1971-Wheel Alignment Specifications Wheel Balancing Tip (F)	Mar. Mar. Apr. June Oct.	22 26 46 52 71 37 41
FRONT END, STEERING Clamp Location for Chevrolet Tie Rod Sleeve (S) Camaro Lower Ball-Joint Inspection (S) Oldsmobile Power-Steering Flow Control Valve Removal (S) Five Easy Steps for Power-Steering Service Front Wheel Alignment (Import Info) VW Front Wheel Alignment, 1968-71 Front End Tune-Up 1971-Wheel Alignment Specifications Wheel Balancing Tip (F) Keep Your Customers' Wheels	Mar. Mar. Apr. June Oct. Oct. Oct.	22 26 46 52 71 37 41 59
FRONT END, STEERING Clamp Location for Chevrolet Tie Rod Sleeve (5) Camaro Lower Ball-Joint Inspection (S) Oldsmobile Power-Steering Flow Control Valve Removal (S) Five Easy Steps for Power-Steering Service Front Wheel Alignment (Import Info) VW Front Wheel Alignment, 1968-71 Front End Tune-Up 1971-Wheel Alignment Specifications Wheel Balancing Tip (F) Keep Your Customers' Wheels Spinning Safely	Mar. Mar. Apr. June Oct. Oct. Oct.	22 26 46 52 71 37 41 59
FRONT END, STEERING Clamp Location for Chevrolet Tie Rod Sleeve (5) Camaro Lower Ball-Joint Inspection (S) Oldsmobile Power-Steering Flow Control Valve Removal (S) Five Easy Steps for Power-Steering Service Front Wheel Alignment (Import Info) VW Front Wheel Alignment, 1968-71 Front End Tune-Up 1971-Wheel Alignment Specifications Wheel Balancing Tip (F) Keep Your Customers' Wheels Spinning Safely	Mar. Mar. Apr. June Oct. Oct. Oct. Nov.	22 26 46 52 71 37 41 59
FRONT END, STEERING Clamp Location for Chevrolet Tie Rod Sleeve (5) Camaro Lower Ball-Joint Inspection (S) Oldsmobile Power-Steering Flow Control Valve Removal (S) Five Easy Steps for Power-Steering Service Front Wheel Alignment (Import Info) VW Front Wheel Alignment, 1968-71 Front End Tune-Up 1971-Wheel Alignment Specifications Wheel Balancing Tip (F) Keep Your Customers' Wheels Spinning Safely FUEL SYSTEM Takes Kinks Out of Tubing (F)	Mar. Mar. Apr. June Oct. Oct. Oct. Nov.	22 26 46 52 71 37 41 59
FRONT END, STEERING Clamp Location for Chevrolet Tie Rod Sleeve (S) Camaro Lower Ball-Joint Inspection (S) Oldsmobile Power-Steering Flow Control Valve Removal (S) Five Easy Steps for Power-Steering Service Front Wheel Alignment (Import Info) VW Front Wheel Alignment, 1968-71 Front End Tune-Up 1971-Wheel Alignment Specifications Wheel Balancing Tip (F) Keep Your Customers' Wheels Spinning Safely FUEL SYSTEM Takes Kinks Out of Tubing (F)	Mar. Mar. Apr. June Oct. Oct. Oct. Nov.	22 26 46 52 71 37 41 59 40
FRONT END, STEERING Clamp Location for Chevrolet Tie Rod Sleeve (S) Camaro Lower Ball-Joint Inspection (S) Oldsmobile Power-Steering Flow Control Valve Removal (S) Five Easy Steps for Power-Steering Service Front Wheel Alignment (Import Info) VW Front Wheel Alignment, 1968-71 Front End Tune-Up 1971-Wheel Alignment Specifications Wheel Balancing Tip (F) Keep Your Customers' Wheels Spinning Safely FUEL SYSTEM Takes Kinks Out of Tubing (F) Gets Good Gas Gauge Ground (F)	Mar. Mar. Apr. June Oct. Oct. Oct. Nov.	22 26 46 52 71 37 41 59 40
Clamp Location for Chevrolet Tie Rod Sleeve (S) Camaro Lower Ball-Joint Inspection (S) Oldsmobile Power-Steering Flow Control Valve Removal (S) Five Easy Steps for Power-Steering Service Front Wheel Alignment (Import Info) VW Front Wheel Alignment, 1968-71 Front End Tune-Up 1971-Wheel Alignment Specifications Wheel Balancing Tip (F) Keep Your Customers' Wheels Spinning Safely FUEL SYSTEM Takes Kinks Out of Tubing (F) Gets Good Gas Gauge Ground (F) Warped Air Horn Causes	Mar. Mar. Apr. June Oct. Oct. Nov.	22 26 46 52 71 37 41 59 40 27 28
FRONT END, STEERING Clamp Location for Chevrolet Tie Rod Sleeve (S) Camaro Lower Ball-Joint Inspection (S) Oldsmobile Power-Steering Flow Control Valve Removal (S) Five Easy Steps for Power-Steering Service Front Wheel Alignment (Import Info) VW Front Wheel Alignment, 1968-71 Front End Tune-Up 1971-Wheel Alignment Specifications Wheel Balancing Tip (F) Keep Your Customers' Wheels Spinning Safely FUEL SYSTEM Takes Kinks Out of Tubing (F) Gets Good Gas Gauge Ground (F)	Mar. Mar. Apr. June Oct. Oct. Oct. Nov. Jan. Feb.	22 26 46 52 71 37 41 59 40 27 28 24

Adjusting the Weber 2V		
Carburetor (Import Info) Carburetor Tune-Up in 10	June	54
Easy Steps	July	44
Capri Instrument Gauge	,	
Diagnosis (S)	July	64
Fuel Recommendations for		
Chrysler (S)	July	64
Procedure Changed (S)	July	64
Servicing Truck Air Cleaners	,	-
Is Not That Different	Sept.	64
Stalling Condition with		
Rochester BC Carburetor (F) Chevrolet Quadra-Jet Fuel-	Oct.	59
Inlet Nut Repair (S)	Oct.	68
Deceleration Valve	001.	00
Adjustment on Capri (S)	Nov.	22
Colt Carburetor Float Level		
Check (S)	Nov.	22
Locating and Servicing Truck Fuel Filters	Nov.	45
Pontiac Fuel Hose	1404.	43
Installation (S)	Dec.	20
LUBRICATION		
Servicing the Crankcase		
(Import Info)	Jan.	22
Takes Kinks Out of Tubing (F)	Jan.	27
Why Today's Oil Gets Tired		
Faster	Jan.	46
Cougar Gauges Read High (S) Oil Pan Removal on	Jan.	58
Montego 429 Engine (S)	Mar.	26
Crankcase Seal Removal (F)		34
Vega Oil Pressure Sending		
Unit Installation (S)	Apr.	26
Oldsmobile Oil Leak and		
Tooth Pattern Diagnosis (S)	Apr.	26
Montega Oil Pan Removal (S)		28 37
New Trends in Lubrication Easier Oil Pan Removal (F)		22
Ford Lubrication Fitting	Sept.	22
Installation (F)	Dec.	30
Know When to Change		-
Truck Oil Filters	Dec.	44
NEW CAR CERVIOR		
NEW CAR SERVICE		
What's New in Servicing	F.1.	47
the '71s		41
Engine		44
Tune-Up		46
Drivetrain		47
Brakes		48
	ONTIN	
Le		

(F) = Fix It

Sept.

Sept. 51

Sept. 53

Buick '72

Cadillac '72

Chevrolet '72

RI

Rad

Ne

Lec

Tai

Fre

Mo

Ne

Int

Do

Ch

Alı

The

Hig

"H

Ele

TR

Al

S

Se

SH

Ti Ti

To

W

Si

M

M

THIS YEAR IN MOTOR continued Month Page Cooling System Feb. Emission Control System 52 Feb. Front End, Steering Feb. Suspension 54 Starting, Charging System, Lights Feb. 76 Comfort and Safety 78 Accessories Feb. Specifications for 1971 Passenger Cars Quick Service Data Feb. 55 Wheel Alignment Specifications Tune-Up Data Feb. 66 Major Dimensions, Engine 70 Feb. Data Major Specifications of the 1972 Models Sept. 54 Where to Find Hood Latch, Gas Filler Cap on '72 Cars Oct. 76 Servicing the Ventura II Oct. 100 ROAD SERVICE Buick Lifting Tips (S) Mar. 26 Vega Lift Points for Frame Contact Hoist (S) May Towing Tip on Locked Car (F) 34 May Towing Cadillac with July 24 Sling-Type Equipment (S) '72 Lift Points 54 Nov. '72 Jack Points Nov. 58 Lincoln Towing Precaution (S) 20 How to Start and Tow the '72s ... SUSPENSION Sobering Facts About 'Tipsy' Cars 50 How to Check Riding Heights of Today's Cars May Pontiac Riding Height 64 Revision (S) Aug. Front End Tune-Up Oct. 37 4-Step Test for Shock Absorbers Oct. 42 When and How to Replace **Bulk Joints** 44 **Ball-Joint Replacement on 1965** Pontiac (S) Oct. TRANSMISSION, CLUTCH Transmission for Cold Weather (F) 27 Takes Kinks Out of Tubing (F) 27 Jan. Cadillac Turbo Hydra-Matic Snap Ring Installation (S) 58 Jan. Friction Material Wear on Plymouth A727 Transmission 58 Jan.

	Month	Page
Oil Pump Overhaul (S)	May	28
Transmission Case (S)	May	28
Adjustment (S)	May	28
Easy TorqueFlite Disassembly (F) Automatic Transmission Pump	May	34
Assembly (F) Erratic or No Upshift on	May	34
Mustang (S) Vega Neutral Start-Switch	June	8
Replacement (S)	June	10
Cadillac TCS Switch Test (S) Pinto Clutch Free-Play		62
Adjustment (S) Plymouth Transmission	Aug.	62 70
Problems (S) Oldsmobile Body Assembly	Sept.	70
Tip (S) Aids Needle Bearing	Sept.	
Installation (F)	Oct.	59
Why Truck Clutches Fail Plymouth Transmission	Nov.	50
Synchronizer Ring Change (S) Vega Clutch-Pedal Free Travel	Dec.	30
Adjustment (S)	Dec.	30
Servicing, Selling Winter Tires Dodge Truck Wheel Mounting	Jan.	38
Stud Threads (S) Mustang Tire Shake (S)	Apr.	64
Keep Your Customers' Wheels Spinning Safely	July	
Spinning Sarely	NOA.	40
CAR REGISTRATIONS		
Record 112 Million Vehicles		
on U.S. Highway in '71	Dec.	45
LAYOUT, TOOLS AND EQUIPMENT TIPS		
Who Says a Garage Can't		
Be Beautiful?		64
Power Brake Tester (F)	Aug.	30
Voltmeter (S) Equipment Outlook for	Aug.	64
Service Stations	Nov.	6
NEW CAR DESCRIPTIO	NS	

How the 3 U.S. Minis Compare ..

1971 Front-Drive Subaru Bows

What's New from Chrysler

American Motors '72

Audi 100 LS

and AMC on '72 Models

28

26

Feb.

May

Automotive Shapes of the '70s...

66

10

56

67

Economy Size

Mar.

May

Aug.

Sept. 46

Chevrolet /2	sepi.	40
Chrysler '72	Sept.	45
Dodge '72	Sept.	44
Ford '72	Sept.	38
Imperial '72	Sept.	45
Lincoln '72	Sept.	41
Massaum /72	Sept.	40
Mercury '72		
Oldsmobile '72 Opel 1900	Sept.	52
Opel 1900	Nov.	67
Plymouth '72	Sept.	42
Pontiac '72	Sept.	50
Saab 99E	Nov.	67
RACING AND PERFORM	ANCE	
NACING AND PERFURM	MINUE	
Tobacco Firm Adds \$100,000		
Tobacco Firm Adds \$100,000		
to NASCAR	Jan.	24
Third Indy-Type 500 Race		
Scheduled in East	Jan.	24
Rossi Gang Wins Annual		
Pit-Crew Competition	Jan.	26
SAAB Racing Team Wins		
Baja 1,000 Rally	Jan.	26
Group Insurance Proposed	Juli.	20
Group Insurance Proposed		-
for "Performance" Cars	Jan.	50
Adapter Reduces Damage		
to Sport Wheels	Jan.	50
New Racina Handbook and		
Manual Published	Jan.	52
Rocker Arm Interference in		
1968 Dodge Dart 340		
Engine	Jan.	52
	Jan.	52
High-Performance Batteries	Jan.	32
NASCAR Award of		
Excellence to Permatex	Feb.	16
Raybestos Indy-500 Contest	Feb.	74
Champagne for the Champ's		
Chief Mechanic	Feb.	75
Movies of 1970 Indy and		
California 500 Available	Feb	75
"Plate" Puts Pressure on	, 00.	, ,
	44	12
Pitts at Daytona 500		12
17-Year Campaigner Takes		
Permatex 300	Mar.	14
Radical Radial Tire Appears		
at Daytona New High-Volume Oil Pump	Mar.	68
New High-Volume Oil Pump		
for H-P VWs	Mar	68
To Help You Get Your Bearings	Mar	69
		69
A Collection on H-P Goodies		
Birth of a Racing Machine	Apr.	12
Racing Mechanics Honored		
in Hall of Fame	Apr.	14
Sports Car Driver Praises		
Roll Bar	Apr.	70
"Fino-Vette" Custom Sports	o-day.	, -
Car Uses Corvette Chassis		-
and Power		70
What Is Blueprinting?	Apr.	72
First Leg on the Hard Drive		
for the "Triple Crown"	May	40
4 Leading Contenders and	,,,,	
Their Cars	May	42
Day Chic Day	may	11/2
Drag Strip Racing—		

Clutch Removal on Ford

Jeep Clutch Adjustment (S)

Pontiac Turbo Hydra-Matic

Truck (F)

ge il

RACING AND PERFORM	ANCE		A/C? (Sam)	Mar	28	SERVICE MANAGEMENT		
Power Tuning Coaxes Extra			Trucks Can Be Way Into	mar.	20	Slavest Man in Shan Wants		
Power from Engine	May	45	Service Biz (Sam)	Mar.	28	Slowest Man in Shop Wants Speed-Up Tips (Sam) Se	ept.	26
Racing Calendar		45	AMC: 'Little' Auto Company			Problem of Slippage Hurts	pi.	20
New Racing School at	,,,,,	-	with Big, Big Plans	Mar.	40		ept.	26
Bridgehampton Track	May	72	TV Keeps 'Eyes' on Customers		43	Four-Day Week for Repair		
Leading Contender for			Do You Want Your Son to				ept.	26
Can-Am Championship	June	60	Be a Mechanic?	Mar.	48			10
Tailgating a Must in Motor			Up the Organization—but			Crooked Customers More or		
Sports	June	60	Gradually	Mar.	52	Less? (Sam) O	ct.	30
Free Trip to Indy 500		61	Trying Harder in the			Wants His Salesmen to Stop		
Most Mechanics Love to Tinker		61	Diagnostic Bay	Mar.	74		ct.	30
New Records Set in			Mechanic Training Gives	44	84	Management Seminar Likely		
Crash-Marred Indy 500	July	10	Boys Another Chance Should I Give My Son a Job?	mar.	04	for IGOA		54
Interview with George Bignotti			(Sam)	Anr	6	Service Important to Volvo O	ct.	62
and A. J. Watson	July	12	Partner Doesn't Want to	Apr.		Equipment Outlook for	lass	4
Donahue Dominates Inaugural			Buy New Equipment (Sam)	Apr.	6	Service Stations N Are We Right to Refuse to	lov.	6
Pocono 500	Aug.	10	Are U.S. Mechanics Ready for			Do Disc-Brake Jobs? (Sam) N	lov	28
Chassis Alignment and Wheel			the Metric System?	Apr.	8	Asks for Advice on Quality	104.	10
Balancing at the Indy 500	Aug.	12	Stop That Thief!		44	Control (Sam) N	lov.	28
Aluminum Racers: Quest Still			End of the Annual Model			Does It Pay to Stay Open		
Goes on 55 Years Later		12	Change	Apr.	64	Nights and Saturdays? D	ec.	6
The Million-Dollar Smile	Sept.	14	Why Do You (or Don't You)			Seeks School Course on		
High-Performance Item for			Service Foreign Cars?	May	8		ec.	24
Vega	Sept.	14	Graduate Wants Job but			Wants to Know How to Spend		
"Hot Dogs" Fail to Cut the	_		Lacks Experience (Sam)	May	24	Ad Dollars (Sam) D	ec.	24
Mustard at California 500	Oct.	14	Lots of Machines, but Little			New Elevated Highway De-		
Are Racing Cars Glued	_		Volume (Sam)	May	24	presses Shop Owner (Sam) D	ec.	24
Together?		16	Wants to Go into Business and					
Electric Racer Sets Speed Record	Oct.	78	Needs Information (Sam)	May	24	SERVICE SALES		
TRW Offers Safety Caravan		70	She's Her Husband's		40	OLIVIOL ONLLO		
at NHRA Events	Oct.	78	Right-Hand Man	May	48	Re-Cycling Brings in Customers Je	an.	16
"Rookie" Wins Final			Asia's John Nerlinger	44	50	Sell Emission Control		
Grand Prix Race	Nov.	14	Talks with MOTOR		52	Service in '71 J	an.	36
America's Fastest Woman	N	14	Distaff on the Sales Staff	June	12	Servicing Selling Winter Tires J.		38
on Wheels	NOV.	14	Where Can I Buy Foreign-	luna	20	Put It Where They Can See It F	eb.	38
All-Engine Muscle Cars Displayed	Mari	15	Car Parts? (Sam) Needs Help in Redesigning	June	28	Doing Something for the Kids		
Displayed	1404.	13	Shop (Sam)	lune	28	to Make Parents Your		10
			Can VW Withstand Detroit's	20110	20	Customers A Take Them Out to the	nar.	10
SERVICE MANAGEMENT			'Small' Guns?	June	40	Ball Game A	nr	30
			Is Servicing Foreign Cars		-	Uncovering the Hidden Air	· lass	00
Seeks Info on Painting (Sam)		4	Profitable?	June	76	Conditioner Service Market A	Apr.	41
Is Gas Heat Safe?	Jan.	4	They Laughed When She			Kiddie Care Also Means		
Wants to Be a Car Dealer (Sam)	Jan.	4	Began to Repair Wrecked			Car Care	Aay	32
Wanda Makes It in a Man's			Cars, but Now	July	8	The Glamour of Performance	,	
World	Jan.	18	Want Information on			Can Still Sell Your		
Service Outlook '71	Jan.	29	Rebuilt Parts (Sam)	July	32	Everyday Customer A	Aay	37
Shop Owners Give Their	1	20	Can't Find Job; Questions			The Joy (and Profit) in		
Views on the Coming Year Business Outlook '71		30	Mechanic Shortage (Sam)	July	32	Teaching	une	14
Tire Trends in the '70s		34	Seeks Training Aids on			Tune-Up Volume Sizzles from		32
	Jan.	38	Basic Maintenance (Sam)	July	32	Steam-Cleaning Offer J Make a Pitch for the Recrea-	une	32
Tire Manufacturers Approved Code Marks	1	39	How to Simplify Automotive		0.4	tional Vehicle Market J	une	50
Total Body Service for the	Jan.	37	Parts Catalogs	July	86	Western Hospitality Wins 20	one	-
'Demanding Ones'	lan	42	How Do You Feel About	A		Service Customers a Day J	une	75
What Do You Say to a	Jun.	42	Hiring a Woman Mechanic?	Aug.	6	Shop Owner Scores with		
Customer Who Calls you			Having Bad Luck; Can Diesel Change Picture? (Sam)	Aum	34	Baseball Promotion J	uly	34
a 'Gyp'?	Feb.	4	How Much Inventory Should	Aug.	34	Girls at the Pump: Do They		
Should We Specialize? (Sam)		12	I Really Carry? (Sam)	Aug	34	Sell More Gas?	Aug.	28
Small Town Sales Manager	100.		Worried About Move to	Aug.	-	A Day for Joy and Happiness S	sept.	16
Seeks Greener Pastures			Strange Location (Sam)	Aug	34	5 Winterizing Money-Makers S	sept.	68
(Sam)	Feb.	12	Dottie, the Brake Specialist		50	Used Wheels: To Sell or		10
Wants Promo to Pull in		-	Can a Franchise Really Make	ag.		Not to Sell	ept.	69
Service Department (Sam)	Feb.	12	It in the Auto Service Field?	Aug.	52	[CONTINUED ON	PAGE	75
Mrs. Hyles, Carburetor Expert		4	New Officer Slate for IGOA	-	66	(S) = Service Slants (F) = F	ix It
						1,		